

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(transmission or gearbox) and torque near converter with (input or engine near output)with constant near2 (speed or rpm or revolution)with difference with turbine	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/08/18 14:56

8/ 18/ 08 2:57:44 PM